

HF Sourcing - Sample Inspection Report

Service: Pre-Shipment Inspection (PSI)

Factory Location: Shenzhen, Guangdong, China

Inspection Standard: AQL General II

Verdict: FAIL - Critical defects found before final balance payment

Scope Checked:

- Business license and onsite production status
- Carton quantity and packing condition
- Function checks and macro defect photos
- Supplier rework recommendation and buyer negotiation notes

This sample file is a placeholder for the downloadable report CTA.